

Advanced Medical Innovations

State-of-the-Art Medical Products™

P.O. Box 10233 • Canoga Park, California 91309 • Tel: (818) 701-7171 FAX: (818) 701-9708

<http://www.amiwelisten.com>

email: sales@amiwelisten.com

Toll Free

1-800-426-6476 or 818-701-7180

SAF-T-POLE IRRIGATION TOWER REPLACEMENT PARTS

Price List January 2, 2017

O.R. IRRIGATION TOWER REPLACEMENT PARTS FOR 11101, 11102 and 11103 SAF-T-POLE™

PROD. #	ITEM #	PRODUCT DESCRIPTION	PKG	EACH
55-BRK	(8)	Plunger Bracket Assembly Kit	1 Ea	\$120.70
55-10185	154	Lever Spring (Stainless Steel)	1 Ea	\$12.05
55-11058-SS	2.1	Stainless Steel Washer	1 Ea	\$6.00
55-14131		Top band screw (stainless steel) -- short	1 Ea	\$3.33
55-25015		Shock absorber (Stainless Steel)	1 Ea	\$72.00
55-29202	(3)	Pole Tube (only) -- (Anodized Aluminum)	1 Ea	\$273.34
55-30014	108	Hanger (Stainless Steel)	1 Ea	\$120.95
55-34532	No #	Allen Screw (Stainless Steel)	1 Ea	\$3.33
55-38131		Stopper screw (stainless steel) - Long	1 Ea	\$3.33
55-38316	114	Bushing (Delrin)	1 Ea	\$10.11
55-40089	132	Slider (Delrin)	1 Ea	\$96.75
55-40125	130 (7)	Handle (Aluminum)	1 Ea	\$83.56
55-44444	86	Stopper	1 Ea	\$59.90
55-46259	(1)	Caster	1 Ea	\$12.05
55-46259-BRK	(1)	Dual Casters lockable	1 Ea	\$18.10
55-50025	156 (11)	Lever (Delrin)	1 Ea	\$120.95
55-58025-SS	(2)	Stainless Steel Bolt	1 Ea	\$24.15
55-60132	76	Cable (Stainless Steel) (need to order 2 Crimps)	1 Ea	\$120.95
55-60181		Trunk (Only) -- (Anodized Aluminum)	1 Ea	\$477.95
55-71618	82/88	Crimp	1 Ea	\$2.37
55-78014	74	Pulley (Delrin)	1 Ea	\$24.15
55-78045	No #	45° Pulley (Delrin)	1 Ea	\$36.25
55-90014-A	No #	Steel Pin	1 Ea	\$11.80
55-90014-B	145	Pin Knurled	1 Ea	\$23.90
59-11101-BA	(5)	Base (Anodized Aluminum)	1 Ea	\$599.56
59-11101-CO	(4)?	Cowl (Base Weld Slotted Cover)	1 Ea	\$120.88

Minimum Order \$25.00

Prices do not include tax or freight

Return to AMI for Repair

Please note that if you prefer to send your unit to AMI for repair we request an open PO with a minimum amount of \$500.00 to cover shipment of box(es) for tower's return, replacement parts, labor and return freight. \$750.00 may not cover the total amount of the repair. We will contact you upon review of the unit to advise cost of replacement parts and labor and will not proceed without your authorization if over \$500.00.